

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT--" for such proposals)

5. Lease  
NMNM-03547

6. If Indian, Allottee or Tribe Name

7. Unit Agreement Name

1. Oil Well  Gas Well  Other   
**GAS WELL**

8. Well Name and No.  
**BREECH "F" 45**

2. Name of Operator:  
**Caulkins Oil Company**

9. API Well No.  
**30-039-60004-00C1**

3. Address of Operator: **(505) 632-1544**  
**P.O. Box 340, Bloomfield, NM 87413**

10. Field and Pool, Exploratory Area  
**DAKOTA, MESA VERDE**

4. Location of Well (Footage, Sec., Twp., Rge.)  
**990' F/S 990' F/W SEC. 35-27N-6W**

11. Country or Parish, State  
**Rio Arriba Co., New Mexico**

**12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

| TYPE OF SUBMISSION                                    | TYPE OF ACTION   |
|---|--|
| <input type="checkbox"/> Notice of Intent             | <input type="checkbox"/> Abandonment                         |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Recompletion                        |
| <input type="checkbox"/> Final Abandonment Notice     | <input type="checkbox"/> Plugging Back                       |
|   | <input type="checkbox"/> Casing Repair                       |
|   | <input type="checkbox"/> Altering Casing                     |
|   | <input checked="" type="checkbox"/> Other <u>Pull Tubing</u> |
|   | <input type="checkbox"/> Change of Plans                     |
|   | <input type="checkbox"/> New Construction                    |
|   | <input type="checkbox"/> Non-Routine Fracturing              |
|   | <input type="checkbox"/> Water Shut-Off                      |
|   | <input type="checkbox"/> Conversion to Injection             |
|   | <input type="checkbox"/> Dispose Water                       |

17. Describe Proposed or Completed Operations:

8-16-99      Rigged up.  
                  Pulled 2 3/8" tubing.  
                  Found piston hung up in collar 3 joints from bottom.  
                  Light scale build-up in bottom 3 joints.  
                  Replaced bottom 3 joints with new 2 3/8" tubing.  
                  Re-ran tubing to 7402'.  
                  Nippled up wellhead.

**RECEIVED**  
SEP 21 1999

**OIL CON. DIV.**  
DIST. 3

070 FRACTURING, NM  
99 AUG 25 PM 1:24  
RECEIVED  
RLM

NOTE: The format is issued in lieu of U.S. BLM Form 3160-5

18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT

SIGNED: Robert L. Verquer TITLE: Superintendent DATE: August 17, 1999  
**ROBERT L. VERQUER**

APPROVED BY: \_\_\_\_\_ TITLE: \_\_\_\_\_ DATE: \_\_\_\_\_  
 CONDITIONS OF APPROVAL, IF ANY