



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Los Mochis
Lease No. 2515
Unit Los Mochis Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	X
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 100 is located 100 ft. from N line and 150 ft. from E line of sec. 27
15/16 Sec. and Sec. No. 27 (Twp.) 12 (Range) 12 (Meridian)
Doña Dolores (Field) San Juan (County or Subdivision) Los Mochis (State or Territory)

The elevation of the derrick floor above sea level is 1000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 2-8-51 Total Depth 100.
 Ran 3/4 joints 5 1/2" 17 1/2 lb casing (100) and 120 joints 5 1/2" 35.5 lb
 3-5/8 casing (500'), for a total of 100 joints (100) and 2 1/2" 130 lb
 collar and at 100.
 IV Stage well out at 100.
 Cemented 1st stage with 17 sacks 2 1/2" Portland, 2 1/2 Gal. 1/2 cu ft. Silsonite/sk.,
 1/8" Floccs/sk. Cemented 2nd stage with 5 sacks 2 1/2" Portland, 2 1/2 Gal.
 Casing held 100 gal/30 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Oil Field Services, Inc.

Address San Juan

San Juan, Los Mochis

By Donald E. R.

Title Assistant Director