



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office Santa Fe
Lease No. 078932
Unit Poster

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 6th, 19 57

Well No. 4 is located 1980 ft. from N line and 1980 ft. from W line of sec. 15

NE/4 SW/4 Sec. 15 26N 13W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6164 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

4-27-57 TD 5170'. Ran electric log. Spotted cement plugs as follows:

40 sacks from 4850' to 5000'
40 sacks from 3900' to 4050'
40 sacks from 1950' to 2100'
40 sacks from 1150' to 1300'

20-sack plug in base of 8-5/8" casing and 10-sack plug in top of 8-5/8" casing, which was left in the hole.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may commence.

Company HENSON-MONTIN-GRER DRILLING CORP.

Address 405 1/2 West Broadway

Farmington, New Mexico

By

Title Vice-President



