

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 03491

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL ☐ GAS ☒ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

El Paso Natural Gas Company

3. ADDRESS OF OPERATOR

PO Box 990, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

990'S, 990'W

7. UNIT AGREEMENT NAME

Huerfanito Unit

8. FARM OR LEASE NAME

Huerfanito Unit

9. WELL NO.

60

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREASec. 4, T-26-N, R-9-W
NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6395'GL

12. COUNTY OR PARISH

13. STATE

San Juan

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Abandonment of Gallup formation ☒(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

The Gallup formation has been plugged and abandoned as follows:

Pulled 2 1/16" and 1 1/2" tubing, set packer plug in packer at 6415'. Spotted 2 sks. sand on
top of packer at 6415'.

Set full-bore packer at 5602', filled annulus and squeezed Gallup perforations with 100 sks. cement.

Located leak in 5 1/2" casing between 4193' and 4256'. Set full-bore packer at 4003' and
squeezed leak with 100 sks. cement.Cleaned out to packer at 6415' and ran 197 joints 1 1/2" 2.9#, J-55 tubing, 6409' landed at
6420', with Baker anchor seal assembly to latch into Model "D" packer and set 4000# on packer.

Completed on 3-2-72.

18. I hereby certify that the foregoing is true and correct



SIGNED Original Signed E. H. WOOD

TITLE Petroleum Engineer

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE



*See Instructions on Reverse Side