UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	NM 13752 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
1. oil gas well kx other 2. NAME OF OPERATOR Jerome P. McHugh 3. ADDRESS OF OPERATOR Box 234, Farmington, NM 87401	8. FARM OR LLASE NAME Chaco Plant 9. WELL NO. #9 10. FIELD OR WILDCAT NAME Undesignated PC 11. SEC., T., R., M., OR BLK, AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17 below.) AT SURFACE: 1800' FNL - 990' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec 5 T26N R12W 12. COUNTY OR PARISH 13. STATE San Juan NM 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5938 GR (NOTE: Report results of multiple completion or zone change on form 9-330.)
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen Plugged and abandoned well as follows: May 23, 1979 Spotted cement plug from 1220 - 1100! 	
 Spotted cement plug from 1220 - 1100'. Spotted surface plug from surface to 250' 	

- 3. Cut casing off 4' below ground level.
- 4. June 13, 1979 -- Cleaned location

Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct 7-30-79 _ DATE _ ___ Dugan (This space for Federal or State office use) APPROVED BY ______ CONDITIONS OF APPROVAL, IF ANY: ___ TITLE __

*See Instructions on Reverse Side