

CHACO LTD. 1-J
Sec. 1, T26N, R13W
San Juan County, New Mexico


SLOPE TESTS

Depth

Hole Deviation

500'
950'
1300'



1/4°
1/2°
1/2°



State of New Mexico)
) ss
County of San Juan)

I, Steve S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 18th day of August, 1982.



Notary Public

My Commission Expires Dec 11, 1985