(other)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

5. LE	EASE
NM	02804

	1141 02001				
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 28-6 Unit 8. FARM OR LEASE NAME				
1. oil gas X other	San Juan 28-6 Unit 9. WELL NO.				
2. NAME OF OPERATOR EL PASO NATURAL GAS CO.	58A 10. FIELD OR WILDCAT NAME				
3. ADDRESS OF OPERATOR BOX 289, FARMINGTON, NEW MEXICO	Blanco Mesa Verde				
 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec., 23, T-28-N, R-6-W				
AT SURFACE: 1030'S, 1070'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Rio Arriba New Mexico				
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO. 1 22 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6536 GL				
TEST WATER SHUT-OFF X X X X X X X X X	(NOTE: Report results of multiple completion or zone change on Form 9–330.)				

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11/14/78: Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 36# K-55 surface casing, 206' set at 219'. Cemented with 219 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes.

NOV 2 0 1978

Subsurface Safety Valve: Manu. and Typ 18. I hereby certify/that the foregoing is	De	VQQI Ocac DMT.	Henry Service	u. 5.6		_ Ft.
SIGNED D. Busco	TITLE Drilling Clerk	_ DATE _	_11/15/7	78		
	(This space for Federal or State office use)	501255	2.5	4.13.1	
APPROVED BY	TITLE	DATE	<u> </u>			

-