

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY**

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well  gas well  other \_\_\_\_\_

2. NAME OF OPERATOR  
El Paso Natural Gas Company

3. ADDRESS OF OPERATOR  
Box 289, Farmington, New Mexico 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1580'S, 1130'E  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

5. LEASE  
SF 079729

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Valdez

9. WELL NO.  
3

10. FIELD OR WILDCAT NAME  
Choza Mesa PC Ext.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 16, T-28-N, R-4-W  
N.M.P.M.

12. COUNTY OR PARISH | 13. STATE  
Rio Arriba | New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
7389' G.L.


16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input checked="" type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) _____	

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 7-18-79: Spudded well. Drilled Surface hole.
- 7-19-79: TD 194'. Ran 4 joints 8 5/8", 36#, K-55 intermediate casing, 182' set at 194'. Cemented w/160 cu. ft. cement. WOC 12 hrs. held 1200#/30 minutes.
- 7-29-79: TD 4439'. Ran 151 joints 2 7/8", 6.4#, J-55 casing liner, 4429' set at 4439'. Baffle set at 4428'. Cemented w/260 cu. ft. cement. WOC 18 hours. Top of cement 3600'.



Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_

18. I hereby certify that the foregoing is true and correct

SIGNED *James D. Bradford* TITLE \_\_\_\_\_ DATE \_\_\_\_\_

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE Drilling Clerk DATE July 31, 1979

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

**AUG 6 1979**

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N.M.

*State*