

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 12-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
Name of Operator SUNTEX ENERGY CORPORATION		3. State Oil & Gas Lease No.
Address of Operator P. O. Box 570725, Houston, Texas 77257		7. Unit Agreement Name
Location of Well UNIT LETTER <u>E</u> <u>1845</u> FEET FROM THE <u>North</u> LINE AND <u>790</u> FEET FROM THE <u>West</u> LINE, SECTION <u>26</u> TOWNSHIP <u>28N</u> RANGE <u>1E</u> NMPM.		8. Farm or Lease Name <u>W. A. Maddox</u> <u>Suntex</u>
15. Elevation (Show whether DF, RT, CR, etc.) <u>7207' G. L.</u>		9. Well No. <u>1</u>
12. County <u>Rio Arriba</u>		10. Field and Pool, or Wildcat <u>W. C. Gallop</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
 COMMENCE DRILLING OPS. ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/1/86 Moved workover rig in.

7/2/86 Ran tubing in well with seating nipple, 2 ft. gas anchor, two 4' pupp joints, with bull plug. Tag bridge plug at 1800'.

7/3/86 Set tubing at 1748', ran bottom hole pump, started well to pumping.

7/4/86 Made 8 B/O overnight, well pump off.

7/5/86 Well made 3 B/O, shut well in to restimulate.

7/5/86 Rig still on locations, weather condition causes delay.

9/1/86 Noticed well was pulled by creditor and equipment removed from location.

4/1/87 Weather has delayed operation from 12/20/86 to 4/5/87.

4/25/87 Equipment will be reinstalled and well will be stimulated weather condition permitting.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Frank Hill TITLE President DATE April 27, 1987

Original Signed by FRANK T. CHAVEZ

TITLE SUPERVISOR DISTRICT # 5

DATE APR 30 1987