

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐

2. NAME OF OPERATOR
AMOCO PRODUCTION COMPANY

3. ADDRESS OF OPERATOR
501 Airport Drive Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
990' FNL x 1650' FEL, Section 36,
AT SURFACE: T-28-N, R-4-W
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other) Completion-Perf & Frac		

5. LEASE
NM 14924

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
Valencia Canyon Unit

8. FARM OR LEASE NAME

9. WELL NO.
20

10. FIELD OR WILDCAT NAME
Choza Mesa Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
NW 1/4 NE 1/4 Section 36,
T-28-N, R-4-W

12. COUNTY OR PARISH
Rio Arriba

13. STATE
NM

14. API NO.
30-039-21599

15. ELEVATIONS (SHOW DEPTH OF KDB, AND WD)
7205' GL, 7215' KB

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Completion operations commenced on 4/6/78. Tripped in with tubing and bit. Cleaned out to 4257' PBD. Pressure tested casing to 3400 psi, held OK. Perforated 3952-4168'. Fraced with 161,166 lbs. SN and 80,583 gallons frac fluid. Tripped in with tubing and bit. Drilled frac baffle plate and cleaned out to PBD of 4257'. Production tubing landed at 4172'.

Completion rig released on 4/8/78.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE Area Adm. Supvr. DATE 7/7/78

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

JUL 10 1978