


Correction in liner setting.

Form 9-331a  
(Feb. 1951)



(SUBMIT IN TRIPLICATE) ✓

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.  
Approval expires 12-31-60.

Land Office Santa Fe  
Lease No. 078500-A  
Unit San Juan 26-7 Unit  
14-06-001-459

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 29, 1957

Well No. 68 is located 990 ft. from [N] line and 1650 ft. from [E] line of sec. 31

NE Section 31  
(¼ Sec. and Sec. No.)

2N  
(Twp.)

7W  
(Range)

N.M.P.M.  
(Meridian)

Blanco  
(Field)

Rio Arriba  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 5983 ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

2-1-57. Total Depth 4872'.

Run 99 joints 5-1/2", 15.50#, J-55 liner (2245') set from 2623' to 4868' with 150 sacks regular cement, 150 sacks Pozmix, 2% Gel, 1/8" Flocculants.

Held 1000# for 30 minutes.

Top of cement by temperature survey at 4200'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

By ORIGINAL SIGNED F. W. BOYD

Title Petroleum Engineer

