

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Fe
Lease No	078354
Unit	Riddle /1
	/ KIBLITU
	# EB 1 9 1952
	A OH CON COM

		√ oil	CON. C
S	UNDRY NOTICES AN	D REPORTS ON WELLS	DIST. 3
NOTICE OF INTENT	ION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	77
	ION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
	ION TO TEST WATER SHUT-OFF		
· · -	ION TO RE-DRILL OR REPAIR WELL		
	ION TO SHOOT OR ACIDIZE		
	ION TO PULL OR ALTER CASING	4	
	ION TO ABANDON WELL		
	(INDICATE ABOVE BY CHECK MARK NAT	URE OF REPORT, NOTICE, OR OTHER DATA)	
		February 18	19_52
S. 1 S. 1 S. 1 S. (% Sec. and)	Sec. 17 27N 9N (Twp.) (
Fulcher-K	utzSan_Juan	NEW Mexico Subdivision) (State or Territory)	
(Field	1) (County or	Subdivising) (See or Lettory)	
he elevation o	of the derrick floor above sea leve	l is <u>6357</u> ft.	
	DETAIL	S OF WORK	
		ls; show sizes, weights, and lengths of proposed cats, and all other important proposed work)	sings;
	at 2208. 5-1/2" casing sacks. Cable tools mov	*. Hole was reduced to 4-3/4" was cemented at 2244 with 100 ed on and drilled cement plug ed hole dry. Tested with 500# hole dry & pipe 0.K.	
	d that this plan of work must receive may be commenced.	approval in writing by the Geological Survey befo	re
ompany	Southern Union Cas Comp	any	
Address	1104 Burt Building		
	Dallas, Texas	By H C markan	me.
		TitleDrilling_Superintende	nt