

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 977329

Unit C. H. Morris 160 ac. 977329

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 20, 1956

Well No. 6 is located 660 ft. from S line and 660 ft. from W line of sec. 15

5/4 27N 10E N70W  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Fulcher-Ruta P/C San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6132 ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Work-over performed from May 8 to 13, 1955.

Fractured with 10,200 gal. diesel oil & 15,000# sand.

Pilot test for production before fracture: 57 MCF; afterwards: 391 MCF.

Annual deliverability test in 5/54 had been 37 MCF/462#; annual test after work-over, taken 8/55, was 120 MCF/385#, last figure being allowable effective on 2/1/56.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BYRD OIL CORPORATION

Address 1110 Tower Petroleum Bldg.

Dallas 1, Texas

By A. L. Moerheide, Jr.

Title Production Supt.