

APPROVED **JAN 11 1951**
P. T. McCall

(SUBMIT IN TRIPLICATE)
**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Land Office **Santa Fe**
Lease No. **079115**
Unit **Allen M. Renkin**

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

JAN 8 1951

**U. S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO**

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January, 19**51**

Well No. **2** is located **1650** ft. from **N** line and **990** ft. from **E** line of sec. **13**

N 13 E 13 (Sec. and Sec. No.) **27 E** (Twp.) **12 W** (Range) **N. M. P. M.** (Meridian)

M. Kantz Canyon (Field) **San Juan** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On **January 5, 1951** mudded **692** ft. **10"** casing.
Obtained **100%** water shut off. Tested by bailing

RECEIVED
JAN 22 1965
OIL CON. COM.
DIST. 3

Understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Lee A. Anderson**
Address **P. O. Box 618, Aztec, New Mexico**

*By **Allen M. Renkin***

T. H.