



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **84 00856**
Unit **Unit 1**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 10

1961

Well No. **7-D** is located **1750** ft. from **S** line and **2550** ft. from **W** line of sec. **9**
SW 1/4 Section **9**
 (1/4 Sec. and Sec. No.) **T-47N** **R-2E** **T.M.P.M.**
 (Twp.) (Range) (Meridian)
San Juan **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6297** ft. **0/100**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded 7/6/61
 Ran 9 jts., 196' of 8 5/8" casing, landed at 311' with 285 wt. cement.
 Tested casing with 500# pressure for 30 minutes. No leaks.
 Drilled cement plug 7/8/61
 Tested with 500# pressure for 30 minutes
 No drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Astec Oil and Gas Company**

Address **Drew # 570**
Farmington, New Mexico

ORIGINAL SIGNED BY JOE C. SALMON

By **Joe C. Salmon**

Title **District Superintendent**