

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa	Fe
Lease No	078050	
Unit	NE/4	

CHINDDY MOTICES AND DEDODES ON

SONDR'I NOTICES AN	D REPORTS ON WELLS	
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF XXX	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CAPITAL	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING AP REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	N. S. Prop. " MEXICO	
	FARMINGIL	
(INDICATE ABOVE BY CHECK MARK NAT	URE OF REPORT, NOTICE, OR OTHER DATA)	
	March 23, 1956	
Christine Hughes		
Well No. 6-4 is located 790 ft. from	$\begin{bmatrix} \mathbf{N} \\ \mathbf{X} \end{bmatrix}$ line and 990 ft. from $\begin{bmatrix} \mathbf{E} \\ \mathbf{W} \end{bmatrix}$ line of sec. 4	
NE/4 Sec. 4 T 27-N R 9-W (% Sec. and Sec. No.) (Twp.) (San		
So. Blanco P. C. Ext. San Juan Cou (Field) (County or Sale		
(Courty of add	division) (State or Territory)	
The elevation of the derrick floor above sea level i	s <u>6865</u> ft.	
	OF WORK	
(State names of and expected depths to objective sands; show sizes, we	ights, and lengths of proposed casings; indicate mudding jobs, cement- mportant proposed work)	
farch 11 1056 After drilling to 2014.	miportant proposed work)	
March 11, 1956. After drilling to 29461 (-1/2" OD 15.5# casing and 63 joints 5-1,	with rotary tools, set 10 joints of	
acks cement. Moved off.	72" OD 14# Casing at 2946 with 100	
	s. Three hour test showed no water.	
March 20, 1956. After drilling to 30	of three nour test showed no water.	
ith 17,000 gallons diesel oil, 15 gallo	or Hi-Flo and 20 000# 1 73 1 1	
ith 3,000 gallons diesel oil. Breakdown	Programs 7504 Trianting 20 0 1	
er minute.	rressure 150#. Injection 39.9 barrels	
	Pipe line connection.	
I understand that this plan of work must receive approach Official	<u> </u>	
I understand that this plan of work must receive approval la mitte	g by the Geological Survey before operations may be commenced.	
Company J. Glenn Turner 🛝 🚨	IST AMA	
Address Box 728		
Farmington, New Mexico	B. C. Jew / sa	
	C. Beeson Neal, Agent in Farmington	
U. S. COVERNMENT IMINT	ING OFFICE 16-6437-5	