For (1	m 9- reb. 19	831 a 851)	

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	. Santa Pa
Lease No.	Gitlut-A
I Init	Hancock "B"

TO DOUL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING ON NO.
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABARDONNIEN
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
(INDICATE ABOVE BY CHECK MAP	RK NATURE OF REPORT, NOTICE, OR OTHER DATA)
(included in the control of the cont	<u>August 6</u> , 19.61
Vell No. 4 is located 972 ft. from W/4 Sec. 22 (W Sec. and Sec. No.) (Twp.)	(Range) (Meridian)
ztec Fictured Cliffs (Count	ty or Subdivision) (State or Territory)
(Field)	
he elevation of the derrick floor above sea	level istt.
DET	AILS OF WORK
.04.1	••••
متعملة بالأنبيان وراوا والانتان	sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-
itate names of and expected depths to objective sands; show ing points, and a	r sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement- all other important proposed work)
pudded 8-6-61. Total Depth 115.	J-55 casing (57°) set at 107° with 220 sacks irculated to surface. Held 6007/30minutes.
pudded 5-6-61- Total Depth 115'.	Ten agains (5711) pet at 1071 with 220 sacks
pudded 5-6-61- Total Depth 115'.	Ten agains (5711) pet at 1071 with 220 sacks
pudded 5-6-61- Total Depth 115'.	J-55 casing (97') set at 107' with 220 sacks irculated to surface. Held 600m/30minutes. AUG 1 1 1961
pudded 5-6-61- Total Depth 115'.	J-55 casing (97') set at 107' with 220 sacks irculated to surface. Held 600g/30minutes. AUG 1 1 1961 OIL CON. COM.
pudded 5-6-61- Total Depth 115'.	J-55 casing (97') set at 107' with 220 sacks irculated to surface. Held 600m/30minutes. AUG 1 1 1961
pudded 5-6-61- Total Depth 115'7-61 Ran 3 joints 0 5/8", 24#, a calcium chloride c	J-55 casing (97') set at 107' with 220 sacks irculated to surface. Reld 600g/30minutes. AUG 1 1 1961 OIL CON. COM. DIST. 3
Pudded 5-6-61- Total Depth 115. 7-61 Ren 3 joints 5 5/6, 24, a calcium chloride con control con control con control con control contr	J-55 casing (97') set at 107' with 220 sacks inculated to surface. Held 600/30minutes. AUG 11 1961 OIL CON. COM. DIST. 3
Junderstand that this plan of work must receive approximately contains the contains of the contains the contai	J-55 casing (97') set at 107' with 220 sacks inculated to surface. Held 600/30minutes. AUG 11 1961 OIL CON. COM. DIST. 3
Junderstand that this plan of work must receive approx. El Paso Natural Gas Company	J-55 casing (97') set at 107' with 220 sacks inculated to surface. Held 600/30minutes. AUG 1 1 1961 OIL CON. COM. DIST. 3 ral in writing by the Geological Survey before operations may be commenced.
pudded 5-6-61- Total Depth 115. 7-61 Ran 3 joints 5 5/6, 24, a calcium chloride con control of the calcium chloride con control of the calcium chloride contr	J-55 casing (97') set at 107' with 220 sacks inculated to surface. Held 600/30minutes. AUG 11 1961 OIL CON. COM. DIST. 3