



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. SP - 00072  
Unit Coin

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	XX
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. Coin is located 1690 ft. from N line and 1690 ft. from E line of sec. 16  
16, Section 16, R-28N (Twp.) R-10W (Range) T.M.T.M. (Meridian)  
Angel Road Water Intention (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5004 ft. C.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth - 6413 P.S.T.D. - 6413  
Hard-water (traced with 1000 lbs. water and 90,000 sand)  
Breakdown pressure - 2300  
Treating pressure - 2300  
Shut in pressure - 600  
I.R. - 46 bpm  
Set 1 1/2" 1260' of 2 3/8" tubing, landed at 1281'  
Shut in for gauge.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company AZORES OIL & GAS COMPANY

Address Box - 100,  
Farlington, New Mexico

By ORIGINAL SIGNED BY JOE C. SALMON  
Joe C. Salmon  
Title District Superintendent

