

SUNDRY NOTICES AND REPORTS ON WELLS

1. oil well ☐ gas well ☒ other

Union Texas Petroleum Corporation

P.O. Box 1290, Farmington, New Mexico 87499

AT SURFACE: 794' FNL; 805' FWL

AT TOP PROD. INTERVAL: Same as above

AT TOTAL DEPTH: Same as above

SUBSEQUENT REPORT OF:

(other) _____

1

DECLASS (NOTE: Ref

UOT 17 1983

(NOTE: Report results of multiple completion or zone change on Form 9-340.)

1. MIRUSU. Pull Dakota tubing and set RBP @ 2000'.

2. Log & perforate and frac Pictured Cliffs.

3. Clean out after frac and retrieve BP.

4. Clean out to PBTD 6449'.

5. Rerun 2-3/8" Dakota tubing to 6312' w/production packer @2000'.

6. Complete for dual Dakota/P.C. production w/Dakota producing up 2-3/8" tubing and P.C. producing up the annulus.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

Sr. Petroleum Eng.

DATE October 14, 1983

SIGNED D.M. Pippin

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

NMOCC