

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. NM - 010063
2. Name of Operator Roddy Production Company	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. P. O. Box 2221, Farmington, NM, 87499, 505 - 325 - 5866	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 910 ' FNL - 1700 ' FEL, Section 17, T28N, R11W, NMPM <i>B</i>	8. Well Name and No. USA - Gentle No. 1
	9. API Well No. 30 - 045 - 21928
	10. Field and Pool, or Exploratory Area Pinon Fruitland
	11. County or Parish, State San Juan, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other	<input type="checkbox"/> Dispose Water

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)
January 29, 1997: Check well. No gas bubbles out of 2 7/8 " casing. Moderate bubbling of gas out of corrosion hole in 5 1/2 " casing. Roddy Production will continue to monitor the gas in the annular (5 1/2 X 2 7/8) space until this summer. If it has not depleted by then we will hot tap the annulus and attempt to bleed of the pressure. If it will not bleed down a bradenhead squeeze will be done with adequate cement volume to pump cement to 600 ' plus 100 % excess unless a squeeze is obtained prior to pumping this volume.

RECEIVED
FEB 1 9 1997

OIL CORL. DIV.
BUREAU

THIS APPROVAL EXPIRES SEP 01 1997

97 FEB 10 PM 12:15
070 FARMINGTON, NM

14. I hereby certify the foregoing is true and correct

Signed R. E. Fitch

Title Agent

Date February 6, 1997

(This space for Federal or State office use)

Approved by IS/Duane W. Spencer
Conditions of approval, if any:

Title

Date FEB 11 1997

NMOC