

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other

2. NAME OF OPERATOR
Southland Royalty Company

3. ADDRESS OF OPERATOR
P. O. Drawer 570, Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1795' FNL & 845' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

5. LEASE
SF-080781

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
McClanahan

9. WELL NO.
#19-E

10. FIELD OR WILDCAT NAME
Basin Dakota/Blanco Mesa Verde

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Section 14, T28N, R10W

12. COUNTY OR PARISH
San Juan


13. STATE
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
5784' GR

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <u>Spud and Casing Report</u> <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>



(NOTE: Report results of multiple completion or zone surveys on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

COMPLETED OPERATIONS-

2-07-80 Spudded 12 1/4" surface hole at 7:00 PM, 2-07-80 and drilled to 237'. Set 5 joints (222') of 8 5/8", 24#, K-55 casing at 234'. Cemented with 140 sacks of Class "B" with 1/4# gel flake per sack and 3% CaCl₂. Cement circulated to surface.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____


18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Dist. Prod. Mgr. DATE 2-08-80

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:



[Signature]

*See Instructions on Reverse Side

FEB 11 '80

FARMINGTON DISTRICT.
BY McKuchera

RECORD