Form Approved.
_ Budget Bureau No. 42-R1424

5. LEASE

SF 080724-A

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

. GEOLOGICAL SURVET	•• •• ••	2 d d	5 00	183	•
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9-331-C for such proposals.)	7. UNIT	AGREEMENT		desi	
	8. FARM	OR LEASE NA		1001. 1001.	
1. oil gas	Zachry		- 5	<u> </u>	
well well other	9. WELL	NO.) P	면 하 등	
2. NAME OF OPERATOR	41			4	
Union Texas Petroleum Corporation		OR WILDCAT		<u>.</u>	
3. ADDRESS OF OPERATOR		GallupcE			
P.O. Box 808, Farmington, New Mexico 87499	11. SEC., AREA	T., R., M.; DR	BLK.¾	IND SURVE	Y OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17		รู้ ฮู ซู ซู 2. T28N-ฺºR	7.05.7	25 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	
below.) AT SURFACE: 552 ft./S; 1945 ft./E line		ITY OR PARISH			
AT TOP PROD. INTERVAL: Same as above	San Jua	= .,		Hexico	
AT TOTAL DEPTH: Same as above	14. API N	C. Ter Ci ···	1 14 GM	2 2 2 2	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.		''' 일반	±. 5		
REPORT, OR OTHER DATA	15. ELEV	ATIONS (SHOW			WD)
and the second s		K.B.	á	. ,	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	30				
TEST WATER SHUT-OFF	, r,	o de la companya de l		i n	
SHOOT OR ACIDIZE	e — — — Last	*	:		
REPAIR WELL	(NOTE: Re	eport results of m	nultiple :	completion o	r zone
PULL OR ALTER CASING	ر. ch	nange on Form 9	-330.)		~
MULTIPLE COMPLETE		원칙교육	-		
ABANDON*		기 등 전 등 기 의 기 의 기 의 기 의 기 의 기 의 기 의 기 의 기 의 기	5	1 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2
(other) Ran 16" conductor pipe X	•		ž	ist of the	7
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen	irectionally o	drilled, give su	i give bsurtac	pertinent c ce locations	lates, s and
1. Spudded 12-1/4" hole at 2:30 P.M. 11/30/82.	£± D V	. n			
 Opened 12-1/4" hole to 22" and drilled to 160 Ran 4 joints of 16", 55#, F-25 casing and set 					
4. Cemented conductor pipe with 413 cu. ft. of c					
Plug down at 1:30 A.M. 12/1/82. Cement circu					
5. Waited on cement 11-1/2 hours.				₹ = a o	
·					
				7	
Subsurface Safety Valve: Manu. and Type		Set	@	<u> </u>	Ft.
18. I hereby certify that the foregoing is true and correct			<u> </u>		
SIGNED HERNETH E. KONSY TITLE Area Prod. Sup	t. DATE	<u>December</u>	7, 1	982	
(This space for Federal or State office	·				—
TITLE	D.**	E		21 1	
APPROVED BY TITLE TOTAL CONDITIONS OF APPROVAL, IF ANY:	DAT		.p.,	FOR REI	
		::63:0	ar araba	was a se to be the bill be	

*See Instructions on Reverse Side

FARMINGTON DISTRICT

EEC 1 0 1982