

Expired APD's
BHP Petroleum (Americas), Incorporated

<u>Number/Name/Expiration Date</u>	<u>Location/Lease No.</u>
✓ 413 Gallegos Canyon Unit Expired: August 7, 1993	1245' FSL & 1020' FEL (SE $\frac{1}{4}$ SE $\frac{1}{4}$), Section 7, T. 28 N., R. 11 W., San Juan County, New Mexico Federal Lease No. SF-078780
✓ 419 Gallegos Canyon Unit Expired: August 7, 1993	1075' FNL & 1357' FEL (NW $\frac{1}{4}$ NE $\frac{1}{4}$), Section 27, T. 29 N., R. 12 W., San Juan County, New Mexico Federal Lease No. SF-079907
✓ 415 Gallegos Canyon Unit Expired: August 7, 1993	2335' FNL & 1145' FEL (SE $\frac{1}{4}$ NE $\frac{1}{4}$), Section 18, T. 28 N., R. 11 W., San Juan County, New Mexico Federal Lease No. SF-047019-B

ABANDONED LOCATION

NMSF-078780 et. al. (WC)
3162.3-1.0 (07337)

JUL 20 1994

Mr. Fred Lowery
BHP Petroleum (Americas), Incorporated
P. O. Box 977
Farmington, New Mexico 87499-0977

Dear Mr. Lowery:

Enclosed are your Applications for Permits to Drill (APD's) the wells listed on the enclosed list. Due to no reports of drilling operations commencing prior to expiration, the subject APD's have expired and are returned. Any expired APD may be resubmitted at any time when definite drilling plans are formulated.

You are required to request surface rehabilitation instructions from this office if construction activities have occurred on any of the proposed drill sites. If this office does not receive comment within 30 days, it will be presumed that no construction occurred. Later discovery that construction activities have occurred, may result in assessment of liquidated damages.

Sincerely,

Chip Haraden

for Ken Townsend
Chief, Branch of Drilling
and Production

- Enclosures (4)
1. APD List
2. Three APD's

cc:

New Mexico Oil Conservation Division
1000 Rio Brazos Rd., Aztec, NM 87410 w/list

RECEIVED
JUL 22 1994
OIL CON. DIV.
DIST. 3

F 30-045-28755 08-12-92
 NSL-3145
 F. Loc. 1245/S; 1020/E Elev. 5509 GL Spd. Comp. TD PB
 Cu. ft. Cu. ft. Cu. ft.
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @
 Csg. Perf. Prod. Stim.
 I.P. BO/D MCF/D After Hrs. SICP PSI After Days GOR Grav. 1st Del. Gas
 1st Del. Oil

TOPS		NiTD	X	Well Log	TEST DATA						
Ojo Alamo		C-103		Plat X	Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland		C-104		Electric Log							
Fruitland				C-122							
Pictured Cliffs		Ditr		Dfa							
Chaco		Datr		Dac							
Cliff House		K07116EJ1 NSL-3145 Acres 267.42									
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											

BasinFrCoal Co. SJ S 07 T 28N R 11W U p Oper. BHP Pet Inc
 Loe. Gallegos Canyon Ut No. 413

Gallegos Canyon Unit #413 P-07-28N-11W

BHP PET INC