
TABULATION OF DEVIATION TESTS

CROSS TIMBERS OPERATING COMPANY

DEPTH	DEVIATION
125'	1/4°
274'	3/4°
815'	1-3/4°
1,032'	l°
1,279'	l°
1,778'	3/4°
2,186'	3/4°
2,682'	1°
3,183'	10
3,680'	1-1/4°
4,179'	1°
4,769'	1-1/4°
5,294'	l°
5,780'	1-1/2°
6,283'	10
6,671'	3/4°



<u>A F F I D A V I T</u>

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation tests taken on CROSS TIMBERS OPERATING COMPANY'S Federal "A" #1E, Section 32, T 28 N, R 10 W, San Juan County, New Mexico.

Signed Printed Name Thomas W. DeLong
Title Production Engineer

THE STATE OF NEW MEXICO)

Output

Outp

Notary Public

My Commission Expires: 6:\Forms\Deviation Tests