

ROBERT L. BAYLESS

PETROLEUM PLAZA BUILDING
P. O. BOX 168
FARMINGTON, NEW MEXICO 87499
(505) 326-2659

JICARILLA 452 #1
Section 6, T29N, R3W
990' FSL & 900' FEL
Rio Arriba County, NM

Slope Test

ORIGINAL HOLE

Depth	Deviation
246'	2°
494'	3-3/4°
742'	4-3/4°
990'	5°
1236'	4 1/2°
1361'	4 1/2°
1483'	4 1/2°
1608'	3°
1733'	3°
2020'	4 1/2°
2164'	5 1/4°
2224'	8°
2257'	6°
2314'	9-3/4°
2379'	12°

SECOND HOLE

Depth	Deviation
2166'	5°
2254'	6 1/4°
2285'	10°

THIRD HOLE

Depth	Deviation
1662'	3°
1700'	6°

Measurements previously
report were incorrect
at: 6° @ 2020' and
3° @ 2100', misreadings

STATE OF NEW MEXICO)
COUNTY OF SAN JUAN) S

I, Kevin H. McCord, Petroleum Engineer, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Kevin H. McCord

Subscribed and sworn before me this 16th day of June, 1986.

Eileen Hare
Notary Public

My Commission Expires: 9-20-88

RECEIVED
JUN 17 1986
CON. DIV.
DIST. 3