

I			

Land Office **Santa Fe**

Lease No. **SP-077967**

Unit Gallegos Canyon Unit

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	X	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK)

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Gallegos Canyon Unit

Farmington, New Mexico May 17, 1961

Well No. 90 is located 1190 ft. from N line and 790 ft. from W line of sec. 35.

SW/4 SW/4 Section 35
(1/4 Sec. and Sec. No.)

T-28-N

(Twp.)

R-13-N

(Range)

N.M.P.M.
(Meridian)

North Dakota

(Field)

San Juan

New Mexico

The elevation of the derrick floor above sea level is _____ ft. **(to be reported later.)**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 12-1/4" hole May 11, 1961. 8-5/8" casing was set at 338' and cemented with 200 sacks containing 2 percent Calcium Chloride circulated. After waiting on cement to set, tested water shut off with 600 pounds for 30 minutes with no pressure drop. Reduced hole to 7-7/8" at 338' and resumed drilling operations.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum Corporation

Address Box 400

Farmington, New Mexico

Attn: L. O. Spear, Jr.

Original signed by
R. M. GAUER, JR.

By

Title Senior Petroleum Engineer