

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078853
Unit _____

0			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 820 15 is located 990 ft. from N line and 990 ft. from E line of sec. 32
SR 4, Sec. 32 T 28N R 11W N. M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
West cuts San Juan N. M.
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5043 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Casing sundry:

8-5/8" surface casing - 95' with 50 sacks cement

5-1/2" production casing - 192' with 150 sacks cement



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company R & O Drilling Co., Inc.

Address 250 W. 57th St.

New York 19, N.Y.

By R. Schwartz

Title office mgr.