

A. P. Klee

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078903
Unit _____

Payne

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Report of test for water shut off</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 26, 19 52

Payne
Well No. 5 is located 1650 ft. from [N] line and 1650 ft. from [E] line of sec. 35


NW 1/4 Sec. 35 (1/4 Sec. and Sec. No.)
28N 12W NMPM
(Twp.) (Range) (Meridian)
West Kutz San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5953 ft. (Ground)
5961.00

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

8/28/52 TD 1713'. 6 5/8" casing set at 1713' and cemented to the surface. Bottom two joints left full of cement. Attempted to pressure up with Baker hand pump. Could not build up pressure. Hole takes water at rate of 0.4 bbl./hr., with no surface pressure, indicating leak in pipe. Well shut in waiting on equipment to repair leak.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Benson and Montin

Address 315 1/2 West Main St.
Farmington, N. M.

By Albert R. Greer
Title Field Sup't.

