

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa Fe
Lease No. 078604
Unit I-300-844

Gallegos Canyon Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 13

1952

Well No. 14 is located 660 ft. from XXXX [N] line and 660 ft. from XXXX [E] line of sec. 26
SW/4 Sec. 26 26N 12W NMPM
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
West Kutz San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5840 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pictured Cliffs sand test. Estimated depth 1800'
 Surface Casing: 80' of 40# size 7/8" - Cemented to the surface.
 Production Casing: 1550' of 17# size 7" - Cemented with 100 sacks.

If commercial production is indicated, the producing section will be shot with nitroglycerin.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BENSON AND MONTINAddress 315 1/2 West Main St.Farmington, N. M.By Albert R. Greer
Albert R. Greer
Title Field Sup't.


Company BENSON MONTIN

Lease _____ Well No. 14

Sec 26 T 28 N R 12W N.M.P.M.


Location 660' from south line and 660'
from west line

San Juan County New Mexico



This is to certify that the above plat
was prepared from field notes of actual
surveys made by me or under my supervision
and that the same are true and correct to
the best of my knowledge and belief

Robert L. Maddox Jr.
Robert L. Maddox Jr.
Registered Professional
Engineer and Land Surveyor
N.Mex. Reg. No. 1426



Surveyed July 15, 1952