

COPY TO O. C. C.

Budget Bureau 42-R588.2
Approval expires 12-31-52

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **I-149-Ind. 8477**
Unit **I-300. 844**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	☒	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 8, 1953

Well No. **45** is located **1860** ft. from **N** line and **1930** ft. from **E** line of sec. **29**

NE/4 SW/4 Sec. 29
(1/4 Sec. and Sec. No.)

28N
(Twp.)

12W
(Range)

N.M.P.M.
(Meridian)

West Mesa
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **5565** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pictured Cliffs Sand Test. Estimated depth 1500'.

Surface Casing: 80' of used 8-5/8" OD 26# cemented to surface.

Production Casing: Approximately 1400' of new 5-1/2" OD 14# cemented with 100 sacks.

If commercial production is indicated, the producing section will be shot with nitroglycerin.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.


Company **REASON-NORTH**

Address **315 1/2 West Main**

Farmington, New Mexico

By **Albert R. Green**

Title **Field Superintendent**



Land Office _____
License No. _____
Unit _____

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO ABANDON WELL	
NOTICE OF INTENTION TO PULL OR ALTER CASING	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	
NOTICE OF INTENTION TO DRILL	
SUBSEQUENT REPORT OF WATER SHUT-OFF	
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
SUBSEQUENT REPORT OF ALTERING CASING	
SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
SUBSEQUENT REPORT OF ABANDONMENT	
SUPPLEMENTARY WELL HISTORY	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

_____ 19____

Well No. _____ is located _____ ft. from _____ line and _____ ft. from _____ line of sec. _____

_____ (Range) _____ (Twp.) _____ (Sec. and Sec. No.)
_____ (County or Subdivision) _____ (State or Territory) _____ (Field)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show slugs, weights, and lengths of proposed casing; indicate mudding jobs, cementing, and all other important proposed work.)



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.


Company _____
Address _____
By _____
Title _____

RECEIVED

OCT 9 1953

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

COMPANY Benson Martin
LEASE Gallardo Canyon Unit Well #45
SECTION 29 T28N R12W NMPM
LOCATION 1930 from west line
1800 from south line
San Juan County, New Mex.



This is to certify that the above
was prepared for the purpose of
actual conveyance by me
and is correct to the best of my
knowledge and belief.

RECEIVED
OCT 19 1953
OIL CON. COM.
DIST. 3

Robert L. Martin
Robert L. Martin
Robert L. Martin
Engineer License No. 1426