Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No. NMSF-078828A

L					
E	6	If Indian	Allottan	as Taiba	Man

abandoned well. Use form 3160-3 (APD) for such proposals							
SUBMIT IN TRIPLICATE - Other instruc	ctions on reverse side. OCT 200	7. If Unit or CA/Agreement, Name and/or No.					
Type of Well Oil Well	S 167	8. Well Name and No. GALLEGOS CANYON UNIT 174					
2. Name of Operator Contact: AMOCO PRODUCTION COMPANY	CHERRY HLAVA E-Mail: hlavacl@pp.com	9. API/Well No. 30-045-07165					
^{3a.} Address P.O. BOX 3092 HOUSTON, TX 77253	3b. Phone No. (include area code) Ph: 281.366.4081 Fx: 281.366.0700	10. Field and Pool, or Exploratory BASIN DAKOTA					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description	1)	11. County or Parish, and State					
Sec 28 T28N R12W Mer NESW 2510FSL 1850FWL		SAN JUAN COUNTY, TX					

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION □ Acidize □ Deepen □ Production (Start/Resume) ■ Water Shut-Off Notice of Intent □ Alter Casing ☐ Fracture Treat □ Reclamation ■ Well Integrity ■ Subsequent Report □ Casing Repair ■ New Construction □ Recomplete □ Other ☐ Final Abandonment Notice ☐ Change Plans □ Plug and Abandon ☐ Temporarily Abandon ☐ Convert to Injection □ Plug Back ■ Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) determined that the site is ready for final inspection.)

Amoco Production Company requests permission to plug and abandon the subject well as per the attached procedure.

Should you have any technical questions please contact Allen Kutch @281-366-7955. For administrative concerns please contact Cherry Hlava @281-366-4081

14. I hereby certify that the foregoing is true and correct. Electronic Submission #7292 verified For AMOCO PRODUCTION COM Committed to AFMSS for process	IPANY, sent to the Farmington			
Name (Printed/Typed) CHERRY HLAVA	Title AUTHORIZED REPRESENTATIVE			
Signature	Date 09/20/2001			
THIS SPACE FOR FEDERAL	L OR STATE OFFICE USE			
Approved By	Title Date 10/23/01			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

SJ Basin Well Work Procedure

Well Name:

GALLEGOS CANYON UNIT #174

Version:

Date:

SEPTEMBER 19, 2001

Budget:

Repair Type:

PLUG & ABANDON

SAP Code:

Objective: P&A WELL

- TOH and strap 5980' 2 3/8".
- Set cement plugs.
- Cut off wellhead & install dry hole marker.

Pertinent Information:

Location:

T28N-R12W-Sec28

API#:

County:

San Juan New Mexico FlacWell:

30-045-07165

State: Horizon:

Basin Dakota

Engr:

Procedure:

- 1. Check anchors. MIRU.
- 2. Check and record tubing, casing, and bradenhead pressures.
- 3. Blow down well. If necessary, kill with fresh water.
- 4. Nipple down WH. NU BOPs. Pressure test to 500 psi.
- 5. TOH and strap 5980' of 2 3/8" tbg.
- 6. RU wireline and set4 1/2" CIBP at 5850'. TIH with tbg open ended to 5850'.
- 7. Pressure test csg to 500 psi for 15 minutes. Plug #1 (5750' 5850'), balance 8 sx Cl. B cement inside csg. PUH to 5028'.
- 8. Plug #2 (4878' 5028'), balance 12 sx inside casing. PUH to 2317'.
- 9. Plug #3 (2167' 2317'), balance 12 sx inside casing. PUH to 1407'.
- 10. Plug #4 (1257' 1407'), balance 12 sx inside casing. PUH to 402'.
- 11. Plug #5 (0' 402'), mix 31 sx to circulate good cement to surface. POH.
- 12. ND BOP & dig cellar. Cut off wellhead and top off casings as needed.
- 13. RD rig. Remove deadmen. Install dry hole marker.
- 14. Restore location as per BLM requirements.







Job separation sheet

Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					/VMSF-078828 A 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TR	7. If Unit or CA/Agreement, Name and/or No.						
Oil Well A Gas Well	Other	(***) Size	APR 2002	8. Well Na	me and No		
2. Name of Operator	, Contact	Cherry Hour	L Carry	Gallegos	Canyon 4	nit 174	
BP America Prod	duction company	Phone No. (Includ		9. API Wel			
P.O. Box 3092 Hou		81-366-488			5-07165 Pool, or Explora		
4. Location of Well (Footage, Sec.	, T., R., M., or Survey Description)	D. 200 /401			Datota	tory Area	
Sec 28 T28N R121		11. County or Parish, State					
40 01701/ 40	DD ODDI I TO DOWNER TO U				an Count		
12. CHECK AP	PROPRIATE BOX(ES) TO INI			EPORT, OR	OTHER DAT	<u> </u>	
1 TPE OF SUBMISSION		1 Y	PE OF ACTION		 -		
Notice of Intent	Alter Casing I	Deepen Fracture Treat	Production (State		Water Shut-0 Well Integrit		
Subsequent Report	·	New Construction	☐ Recomplete	(Other	ther	
Final Abandonment Notice		lug and Abandon	Ξ,		andon		
	Convert to Injection If	lug Back	Water Disposal				
anuted 10/23/01	Production Company regularies Detween Charlie Perri						
	ched T; A subsequen	t Report			2002 APR 15 PM 1	RECEIVE	
14. I hereby certify that the foregoin	g is true and correct	1					
Name (Printed/Typed)		Title P		1	≤ ~		
Cherry Hlava	/	X	egulatory Av	nalyst	-		
Signature Churry	Hlava		1-10-02				
	THIS SPACE FOR F	EDERAL OR S	TATE OFFICE US	.		_	
Approved by		Т	tle	Da	te		
	attached. Approval of this notice does alor or equitable title to those rights in the conduct operations thereon.	not warrant or	ffice		PTE) FOR	RECOR	
Title 18 U.S.C. Section 1001 and Ti States any false, fictitious or fraudule	tle 43 U.S.C. Section 1212, make it a creent statements or representations as to an	ime for any person ly matter within its j	knowingly and willfull urisdiction.				

Gallegos Canyon Unit #174 Subsequent T&A Report April 10, 2002

4/3/02 Spot Equipment, RU/flw line. Take readings. SDFN

4/4/02 TIH & set CIBP @ 5850'. Circulate hole. Could not pressure tst csg. SDFN.

4/5/02 Pressure test csg to 550 psi. Held ok. RD/FMC. TIH. W/ 1 jt., SN., & 184 jts. Landed Tbg @5802.25'. NDBOP, NUWH. RDSU & Equipment moved off.