

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 070000

Unit I-Sec. 24

Gallegos Canyon Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 26, 1952

Well No. 17 is located 770 ft. from [N] line and 770 ft. from [E] line of sec. 20
NE 1/4 Sec. 20 (1/4 Sec. and Sec. No.)
West Main (Field)
20N (Twp.)
San Juan (County or Subdivision)
12W (Range)
North (Meridian)
New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 9665 ft. (Ground)
5673 KB

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7/30/52 TD 1405' (3' under 5 1/2" casing)
 Bailed hole dry and tested 2 hours for water shut off.
 Hole tested dry.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Benson and Martin

Address 1001 31st West Main St.

Farmington, N. M.

By Albert E. Green
 Albert E. Green
 Title Field Sup't.

OIL CONSERVATION COMMISSION
AZTEC DISTRICT OFFICE

No. Copies Received **2**

DISTRIBUTION

	NO. FURNISHED	
Operator		
Santa Fe	1	
Proration Office		
State Land Office		
U. S. G. S.		
Transporter	1	✓
File		

