

COPY FOR
STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
SUBMIT IN TRIPLICATE TO
DISTRICT OFFICE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078985
Unit Gallegos Canyon

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<div>RECEIVED JAN 10 1952 OIL CON. COM. DIST. 3 XX</div>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 9, 1952

Well No. 6 is located 1340 ft. from N line and 1110 ft. from E line of sec. _____
SW Sec. 22 28N 12W NMPH
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5660 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

T.D. 1498'; P.B.T.D. 1478'

1-6-52 - Shot with 86 qts. SWG 1442-78'.

1-8-52 - Gauged 1,340 MCF 22 hours after unloading hole following shot.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Denson and Montin

Address 1501 Petroleum Building

Oklahoma City, Oklahoma

By Albert R. Greer

Title Petroleum Engineer

5 cc - USGS, Farmington
1 cc - Denson & Montin, Oklahoma City
1 cc - Stanolind, Farmington
1 cc - File