

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **I-149-Ind-8475**
Lease No. **1-See. 844**
Unit **Gallegos Canyon Unit**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 26, 19**52**

Well No. **18** is located **1690** ft. from **12 1/2** line and **900** ft. from **12 1/2** line of sec. **21**
NE/4 **21** **28N** **12 1/2 W** **107N**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian) **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5576** ft. (**Ground**)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7/22/52 TD 1377' (3' under 5 1/2" casing)
Drilled hole dry and tested one (1) hour for water shut off.
Hole tested dry.
Measured 10 MCF gas @ 1377'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **BENSON AND MONTIN**

Address **315 1/2 West Main St.**

Farmington, New Mexico

By **Albert E. Greer**
Title **Field Sup't.**

OIL CONSERVATION COMMISSION

AZTEC DISTRICT OFFICE

No. Copies Received 2

DISTRIBUTION

	NO. FURNISHED	
Operator		
Santa Fe	1	
Peroration Office		
State Land Office		
U. S. G. S.		
Transporter		
File	1	