

WELL NO. 5 LEASE Gallegos Canyon Unit
 OPERATOR Benson & Montin

COMPLETION SUMMARY

SCHEDULE OF DATES	MONTH	DAY	YEAR
LOCATION XXXX Surveyed	4	28	51
ROTARY RIGGING UP	9	24	51
DRILLING COMMENCED	9	25	51
DRILLING COMPLETED	10	13	51
FIRST PRODUCTION	10	7	51
POTENTIAL TEST	11	1	51
OFFICIAL COMPLETION			
PLUGGED (IF DRY HOLE)			

LOCATION DATA			
FIELD <u>Wildcat</u>	FORMATION COMPLETED IN <u>Pictured Cliffs</u>		
COUNTY <u>San Juan</u>	STATE <u>New Mexico</u>		
LOCATION <u>1980</u>	FEET <u>South</u> OF THE <u>North</u> LINE		
AND <u>990</u>	FEET <u>West</u> OF THE <u>East</u> LINE OF		
SECTION <u>13</u>	TOWNSHIP <u>28 N</u>	RANGE <u>13 W</u>	
SURVEY	BLOCK NO.		
ELEVATION GROUND <u>5617</u>	ELEVATION K. B. <u>5627</u>		
ELEVATION CASINGHEAD <u>5618</u>	WELL SPACING ACRES		

BRIEF DESCRIPTION OF COMPLETION

FORMATION, OPEN HOLE OR PERF., SINGLE, DUAL, TRIPLE, OIL, GAS, WATER, DRY, ETC.

Drilled to 1336 with rotary. Cored 1336 - 1470. Plugged back 1470 - 1441 with calseal. Shot 1394 - 1441 with 110 qts. SNG.

Casing: 10 3/4" at 100' with 90 sacks;
 5 1/2" at 1381' with 90 sacks.

Production Tests:

Natural - 1,370 MCF per day (open 27 hours)
 from 1381-1470, no water.

After Shot - 4,830 MCF per day (State Test - open 3 hours)
 from 1381-1441. Shut in pressure 461#.

- (1) This is one of seven exploratory wells drilled to test the Pictured Cliffs formation.
- (2) No participating areas have yet been established.

San Antonio Canyon Unit
Hanson & Montin

CONSTRUCTION REPORT

DATE	TIME	LOCATION	DEPTH	REMARKS
11	11	11	11	11
10	10	10	10	10
9	9	9	9	9
8	8	8	8	8
7	7	7	7	7
6	6	6	6	6
5	5	5	5	5
4	4	4	4	4
3	3	3	3	3
2	2	2	2	2
1	1	1	1	1
0	0	0	0	0
1980	1980	1980	1980	1980
1981	1981	1981	1981	1981
1982	1982	1982	1982	1982
1983	1983	1983	1983	1983
1984	1984	1984	1984	1984
1985	1985	1985	1985	1985
1986	1986	1986	1986	1986
1987	1987	1987	1987	1987
1988	1988	1988	1988	1988
1989	1989	1989	1989	1989
1990	1990	1990	1990	1990
1991	1991	1991	1991	1991
1992	1992	1992	1992	1992
1993	1993	1993	1993	1993
1994	1994	1994	1994	1994
1995	1995	1995	1995	1995
1996	1996	1996	1996	1996
1997	1997	1997	1997	1997
1998	1998	1998	1998	1998
1999	1999	1999	1999	1999
2000	2000	2000	2000	2000
2001	2001	2001	2001	2001
2002	2002	2002	2002	2002
2003	2003	2003	2003	2003
2004	2004	2004	2004	2004
2005	2005	2005	2005	2005
2006	2006	2006	2006	2006
2007	2007	2007	2007	2007
2008	2008	2008	2008	2008
2009	2009	2009	2009	2009
2010	2010	2010	2010	2010
2011	2011	2011	2011	2011
2012	2012	2012	2012	2012
2013	2013	2013	2013	2013
2014	2014	2014	2014	2014
2015	2015	2015	2015	2015
2016	2016	2016	2016	2016
2017	2017	2017	2017	2017
2018	2018	2018	2018	2018
2019	2019	2019	2019	2019
2020	2020	2020	2020	2020

Trilled to 1930 with rotary. Cored 1930 - 1940. Flipped back 1940 - 1941 with
classical. Also 1941 - 1942 with 110 ft. and.

Grading: 1941 at 100' with 10 acres;
1942 at 1941 with 10 acres.

Production factor:

Interval - 1,370 ft. per day (open 18 hours)
from 1941-1942, no water.

After flow - 1,630 ft. per day (open 18 hours)
from 1941-1942, show in pressure 1941.

(1) This is one of seven exploratory wells drilled to test a fractured Cliffs
formation.

(2) No participating areas have yet been established.