

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Juan
Lease No. 77-2216
Per C. J. Holder

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

C. J. Holder Water Well Farmington, New Mexico January 23, 1962

Well No. 1 is located 910 ft. from N line and 1850 ft. from E line of sec. 16


NE/4 Section 16 T-28-N R-13-W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Water Supply Source San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft. (To be reported later.)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Strudded 15" hole on January 18, 1962. Drilled to 220', then reamed hole to 17" to 206'. Casing set at 206' with 225 sacks Incor cement. Circulated 65 sacks. After waiting on cement, tested casing with 900 PSI for 15 minutes with no drop in pressure. Reduced hole to 11" at 206' and resumed drilling.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San American Petroleum Corporation

Address P.O. Box 430

Farmington, New Mexico

Attn: L. G. Speer, Jr.

By _____

Title Senior Petroleum Engineer