

X			

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 077976
Unit Jones

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF ACIDIZING ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ACIDIZING ACIDIZING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 8th, 19 60

Well No. 4 is located 600 ft. from N line and 600 ft. from E line of sec. 17
NW/4 NW/4 Sec. 17 28N 13W N.M.P.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5989 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

8-23-60 Cleaned out to 5671'. Perforated 5620-34' with 4 jet shots per foot. Spotted 300 gallons 15% MCA at 5620'. Set packer at 5600'. Breakdown pressure 1600#, broke to 700#. Injected acid at 1350#. Swabbed hole dry.
 8-24-60 Perforated 5558-86' with 2 jet shots per foot. Spotted 300 gallons 15% MCA. Set packer at 5600'. Displaced acid into formation. Maximum pressure 1500#, broke to 700#. Reset packer at 5538'. Swabbed hole dry.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BENSON-MONTIN-GREEK DRILLING CORP.
 Address 158 Petroleum Center Building
Farmington, New Mexico
 By _____
 Title Vice-President