

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

SF-078904

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ ON  
☐ SAN  
☒ OTHER

2. NAME OF OPERATOR

Amoco Production Company

3. ADDRESS OF OPERATOR

501 Airport Drive, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1500' FNL x 1850' FWL

7. UNIT AGREEMENT NAME

Gallegos Canyon Unit

8. FARM OR LEASE NAME

9. WELL NO.

242

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR B.L. AND  
SURVEY OR AREA

SE/NW Sec. 24, T28N, R12W

12. COUNTY OR PARISH 13. STATE

San Juan

NM

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, ET, OR, etc.)

5707' RDB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Moved in and rigged up service unit 6-1-84. Set a bridgeplug at 6031' and a packer at 6000'. Tested bridgeplug to 2000 psi and it held. Spotted two sacks of 20-40 frac sand on top of bridgeplug. Tested casing and it held, no casing leak found.

Landed 2-3/8" tubing at 6181' and released the rig on 6-7-84.

RECEIVED

AUG 29 1984

OIL CON. DIV.  
DIST. 3

RECEIVED  
AUG 27 1984  
BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

18. I hereby certify that the foregoing is true and correct

SIGNED

Original signed by  
B. D. Shaw

TITLE Adm. Supervisor

DATE 8-14-84

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

AUG 27 1984

NMOCC  
\*See Instructions on Reverse Side

FARMINGTON RESOURCE AREA  
BY [Signature]