

A. P. Kline

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 078903 *A (note)*

Unit I-300. 844

Gallegos Canyon Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 11 is located 660 ft. from S line and 660 ft. from W line of sec. 34
34/4 Sec. 34 29N 12E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
West Kuts San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 5229 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

10/21/52

7" casing set at 1495'.
TD 1796'. 3 hr. bailing test showed no water.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Benson and Moutin

Address 315 1/2 West Main St.

Farmington, N. M.

By Albert R. Greer
Albert R. Greer
 Title Field Sup't.

OIL CONSERVATION COMMISSION
AZTEC DISTRICT OFFICE

No. Copies Received 2

DISTRIBUTION

	NO. FURNISHED	
Operator		
Santa Fe	1	
Flotation Office		
State Land Office		
U. S. G. S.		
Transporter		
File	1	<input checked="" type="checkbox"/>

