UNITED STATES DEPARTMENT OF THE INTERIOR **UNITED STATES BUREAU OF LAND MANAGEMENT**

Sundry Notices and Reports on Wells

Control of the Contro		
	5.	Lease Number SF 078863
1. Type of Well Gas	6.	If Indian, All. or Tribe Name N/A
	7.	Unit Agreement Name
2. Name of Operator M&G Drilling Company, Inc.		N/A
Midd Drilling Gompany, mo.	8.	Well Name & Number
3. Address & Phone No. of Operator		Krause #64
C/O KM Production	9.	API Well No.
P.O. Box 2406, Farmington, NM 87499 505-325-6900	10.	30-045-22856 Field and Pool
4. Location of Well, Footage, Sec., T, R, M 1109' FSL & 1125' FEL, Sec. 29, T28N, R11W	10.	Kutz Farmington
1109 1 3E & 1123 1 EE, 366. 23, 12314, 111111	11.	County & State San Juan County, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OT	HER D	
Type of Submission Type of Action		
Notice of Intent Abandonment Change of Plans		
Recompletion New Construction		
X Subsequent Report Plugging Back Non-Routine Fractu	iring	
Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection	rtion	
Other -		
13. Describe Proposed or Completed Operations		
MARC Deilling plugged and chandened this well on August 29, 100	7	
M&G Drilling plugged and abandoned this well on August 28, 199 per the attached P&A report.		
		The second secon
	j C	
	37.	
14. I hereby certify that the foregoing is true and correct.	Belgio service non	entra dia kaominina dia kaomin
Signed /// Title Agent // Kevin McCord		Date <u>9/5/97</u>
	<u> </u>	
(This space for Federal or State Office use) APPROVED BY/S/ Duage W. Spencer Title		Date SEP 2 9 1997
APPROVED BY/S/ Duane W. Spencer Title CONDITION OF APPROVAL, if any:		Date (103)

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211

M&G Drilling Company c/o KM Production Company Krause #64 1109' FSL and 1125' FEL Sec. 29, T-28-N, R-11-W, San Juan County, NM SF-078863 September 5, 1997

Plug & Abandonment Report

Cementing Summary:

Plug #1 with 64 sxs Class B cement inside casing from 1245' to 438' to isolate Fruitland perforations and cover Ojo Alamo top.

Plug #2 with 24 sxs Class B cement from 169' to surface in 4-1/2" casing.

Plugging Summary:

Notified BLM on 8/27/97

8-28-97 Safety Meeting. Road rig and equipment to location. RU rig and equipment. Layout relief line to pit. Bleed well down. NU BOP and rig floor. Tag fill at 1245'. M. Deaton, BLM approved combining Plug #1&2. Plug #1 with 64 sxs Class B cement inside casing from 1245' to 438' to isolate Fruitland perforations and cover Ojo Alamo top. POH and tally 36 joints 1-1/4" tubing, 1234'. RIH with 6 joints tubing. Load casing with 5 bbls water and pressure test to 500#, held OK. Plug #2 with 24 sxs Class B cement from 169' to surface in 4-1/2" casing. POH and LD tubing, shut in well and WOC. ND wellhead and BOP. Cut off casing and found cement down 32' in casing and casing annulus. Mix 44 sxs Class B cement to fill casing and annulus; then install P&A marker. RD rig and equipment. Road rig and equipment to A-Plus Yard. M. Deaton, BLM was on location.