) PAGE 1 of 2 9-331 1973

A STORY IS

into His

CHARLES

UNITED STATES

9_331 1973	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE 0.8112 3 3.85
DEPARTMENT OF THE INTERIOR	SF - 078807 - A
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	Gallegos Canyon Unit
1 all	8. FARM OR LEASE NAME
well gas to other	9. WELL NO. 0704 4 775
2. NAME OF OPERATOR	321 জুলাট্ট জ টুট্ট
Energy Reserves Group, Inc. 3. ADDRESS OF OPERATOR	West Kutz Pictured Cliffs
P.O. Box 3280, Casper, Wyoming 82602	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) AT SURFACE: 810' FSL & 1,540' FEL (SW/SE)	Sec. 12 - T28N-R13W
AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE San Juan New Mexico
AT TOTAL DEPTH:	14. API NO. 3445 4 5 4 5
 CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 	<u> </u>
	15. ELEVATIONS (SHOW DF, KDB, AND WD) G.L 5,684; K.B. 5,686
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
FRACTURE TREAT	
SHOOT OR ACIDIZE REPAIR WELL	
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
MULTIPLE COMPLETE CHANGE ZONES	
ABANDON*	
(other) Well History X	Apolition des Micageo Rou Demand de Casan est la Casan est la Casan de la Casa
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	oll marking at the state of the
including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent	rectionally drilled, give subsurface locations and
The above referenced well was spudded @ 3:15 a	절탕하다 뭐 그셨게요
	ಕರ್ತ್ವರ ಆ ಸ್ಥರಕ್ಕೆ
Drld 9-7/8" hole to 123'. Ran 3 jts 17#, H -	40, R-3, ST&C, New casing set @
Plug down 0.6:30 am 3 27 21 good coment water	2% CACL ₂ & 1/4# celloflake 1/sack.
riag down & 0.30 am 3-27-81 good cement return	ns. salaga dan dan dan dan dan dan dan dan dan dan
122'. Cemented w/ 65 sx of class B cement w/2 Plug down @ 6:30 am 3-27-81 good cement return Nipple up and press tested BOPE to 500 psi - PDrld 6-1/4" hole to 1.582' & ran logs.	held O.K. The best of the state
Duld 6 1/44 hala ta 1 5001 0	Transport
Drld 6-1/4" hole to 1,582' & ran logs.	Record guidhickly shows well as an inverse well as an inverse well as an inverse well and the particular posture to show the particular posture to show the
Ran 40 jts - 4-1/2" 0.D., 10.5#, R-3, ST&C, ne	ew casing set 0 ਹੈ, 5781 gemented w/225
$SY \cap F \cap $	0 A F0/ NFD A'- C
Plug down @ 9:30 pm. Good circulation but cmt Subsurface Safety Valve: Manu. and Type	did not circulate. हेवू है है है
	Set @ - 3 1985 Ft.
18. I hereby certify that the foregoing is true and correct	o ei Sie one con e
SIGNED & SILLE Drlg. Supt	DATE 3-31-81 2013
(This space for Federal or State office	e use)
APPROVED BY TITLE	DATE 5 THE THE PARTY OF THE PAR
CONDITIONS OF APPROVAL, IF ANY:	
	dicions of the part of the par
NMOC	10 30 E

*See Instructions on Reverse Side