Form 9-331	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF 078072
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different	Southeast Cha Cha
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas other other	9. WELL NO.
2. NAME OF OPERATOR	39
Hicks Oil and Gas	10. FIELD OR WILDCAT NAME Cha Cha Gallup
3. ADDRESS OF OPERATOR P. O. Box 174, Farmington, N.M. 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1	7 AREA
below.) 1650' from East line and 750' from	Sec. 7, T28N, R13W 12. COUNTY OR PARISH 13. STATE
AT SURFACE: South line AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	
REPORT, OR OTHER DATA	15. ELEVATIONS (NHOW DF, KDB, AND WD)
	5941 Ground 5.54 KB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT SHOOT OR ACIDIZE RECEVED	
C	
PULL OR ALTER CASING OF SOME STATE COMPLETE.	
MULTIPLE COMPLETE	H DOLGAL SURVEY
ABANDON*	DLOGICAL SURVEY INGTON, N. M.
(other)	Hitary
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sincluding estimated date of starting any proposed work. If well i measured and true vertical depths for all markets and zones perticular. 	
	Procesure tested to 3000 psi. Spott
Set retrievable bridge plug at 5415'. 9-18-81.	pated Gallup 5270'-86' with 2 shots
500 gal. of 15% MCA from 5286 to 4786. Perforated Gallup 5270'-86' with 2 shots per foot. Broke down at 1500 psi and established rate of 20 bpm at 1100 psi. Frac	
$\frac{1}{2}$ $\frac{1}$	
4 to 1 to	
crobbod too days put back on him 9/14/01. July 00 July production	
a 21 91 Pulled rods and numb. Acidized Gallup 5270-80 Will 800 gar.	
7 ½ HCL, 800 gals. 17% HF acid, and tailed in with 800 gal. 7½% HCL aci NOV 4 bb 198 two days. Final swab samples 50% oil and 50% water. Put back on pump 9/24/8 COM.	
two days. Final swab samples 50% oil and 50% water. Put back on pully con. com	
retrievable bridge plug and put back on produc	cton.
Subsurface Safety Valve: Manu. and Type	Set @
18. I hereby certify that the foregoing is true and correct	10/05/01
SIGNED // President	
(This space for Federal or State office use)	

*See Instructions on Reverse Side

. TITLE DATE