

PROPERTY MANAGEMENT & CONSULTING, INC.

P. O. BOX 2596

FARMINGTON, NEW MEXICO 87499-2596

(505) 325-5220

02/09/01

New Mexico Oil & Gas Conservation Division
1000 Rio Brazos Road
Aztec, NM 87410

Attn: Charlie Perrin

RE: Packer Leakage Test - Initial
Roddy Production Company, Inc.
Lucerne Federal #6
K-21-28-11

Dear Charlie,

We will be testing this well for communication on February the 16th if it takes that long to stabilize the Pictured Cliffs. If it stabilizes earlier, we will call and notify you of test date.

Sincerely,



Bob Fielder

Tested @ 1:00 pm 2/15/01

Casing (Fruitland Sand) = 519 psig Tubing (PC) = 66 psig.
Opened Csg to atmosphere for ~15 min while monitoring tbq.
Casing pressure dropped to 42 psig. tbq pressure remained constant
No Communication.