

ROBERT L. BAYLESS

PETROLEUM PLAZA BUILDING
P O BOX 168
FARMINGTON, NEW MEXICO 87499
(505) 326-2659

SCHLOSSER #97
623' FSL & 1347 FWL
N SEE. 34, T28N, R11W
SAN JUAN COUNTY, NM

SLOPE TEST

<u>Depth</u>	<u>Hole Deviation</u>
123'	1/4°
600'	1/2°
900'	3/4°
1425'	1°
1990'	1 1/2°

RECEIVED
DEC - 1 1997 BY
OIL COM. DIV.


DISC 3

State of New Mexico)
) ss
County of San Juan)

I, KEVIN H. MCCORD, being first duly sworn,
depose and state that the above and foregoing depth and hole
deviation figures are true and correct to the best of my
information and belief.

Kevin H. McCord

Subscribed and sworn before me this 23rd day of Oct, 1997.



Pamela E Clement
Notary Public

My Commission Expires

5-15-2001

JABO JACOB
VETERINARIO DE ALIMENTOS
OCASION VETERINARIO TRATAMIENTO
ESTADO DE VERACRUZ MEXICO 2010
SERVICIOS VETERINARIOS