UNITED STATES DEPARTMENT OF THE INTERIOR

5.	LEASE
SF	078917
6.	IF INDIAN, ALLOTTEE OR TRIBE NAME
	UNIT ADDESIGNED MANAGE

DEFAITMENT OF THE INTERIOR	SF 11/89 I /
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
	San Juan 29-5 Unit
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas gy	San Juan 29-5 Unit
well well other	9. WELL NO.
2. NAME OF OPERATOR	90
Northwest Pipeline Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota
P.O. Box 90, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OF
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	Sec 35 T29N R5W
AT SURFACE: 1180' FSL & 1750' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Rio Arriba New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD
	7440 GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	-1.4
TEST WATER SHUT-OFF	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zon
PULL OR ALTER CASING	change on Form 9-330.)
MULTIPLE COMPLETE	
ABANDON* ☐ ☐	
(other) "Commence drilling"X	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent of the control o	irectionally drilled, give subsurface locations and to this work.)* O hrs. Drilled to 462'. #, K-55, ST&C csg set @ 455'. 1015 hrs. Did not circ cmt. sks. Job complete @ 1315 hrs.
Subsurface Safety Valve: Manu. and Type	Set @
18. I hereby certify that the foregoing is true and correct	
SIGNED Darlara Title Production Cle	erk DATE August 1, 1978
(This space for Federal or State offi	
ADDDOVED BY	DATE OF TWO
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	UNIT OF THE STATE