

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. 070424

Unit San Juan 29-7 Unit
14-05-001-567

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 14, 1956

Well No. 53 is located 1550 ft. from N line and 600 ft. from E line of sec. 27

Section 27
(1/2 Sec. and Sec. No.)

291

(Twp.)

(Range)

(Meridian)

Blanco

(Field)

Rio Grande
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6304 ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(n 8-10-50) Total Depth 3202'.

ran 104 joints 7 5/8", J-55, 26.4#, casing (3272') set at 3252' with 100 sacks regular cement, 100 sacks Pozmix, 50# Flocele and 4# gel followed with 50 sacks Neat Cement.

Held 1000 30 minutes.

Top of cement by temperature survey at 2890'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 91

Parlington, New Mexico

By Lawell H. Walsh

Title Petroleum Engineer