

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 03599
Unit Graveling

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 22, 1951

Well No. 3 is located 990 ft. from SW line and 1690 ft. from W line of sec. 22

SE 1/4 Section 22
(1/4 Sec. and Sec. No.)

23N
(Twp.)

SW
(Range)

N. M. P. M.
(Meridian)

Blanco Est.
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5657 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

March 21, 1951:

Set 7" casing at 3725' using 625' of H-30, 23 lb. and 3112' of J-55, 20 lb. cemented in two stages.

First Stage - Used 200 sacks Ideal Regular. Top of cement by Temperature Survey 3530'.

Second Stage - (Took at 3225') Used 190 sacks Ideal Regular and 10 sacks Straits Seal. Top of cement by Temperature Survey 1270'.

Held 600 lbs. for 7 hours.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SAH JUAN PRODUCTION COMPANY

Address 102 1/2 North Court Avenue

Farmington, New Mexico

By E. J. Coal
Title Petroleum Engineer