TABULATION OF DEVIATION TESTS LENIS A. SHANE USA NO. 1 PAN AMERICAN PETROLEUM CORPORATION

| DEPTH | DEVIATION |
|--|--------------------------------------|
| 103' 225' 611' 1025' 1089' 1435' 1463' 1815' | 1° 1° 1° 1° 1° 1/2° 1/2° 3/4° 1-1/2° |
| 2258' 2510' 2560' | 1° 1° |

<u>A F F I D A V I T</u>

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation test taken on PAN AMERICAN PETROLEUM CORPORATION'S Lenis A. Shane USA No. 1, Blanco Pictured Cliffs Field, located in the SE/4 SW4 of Section 14, T-29-N, R-9-W, San Juan County, New Mexico.

said County and State this 14th day of February, 1968.

My Commission Expires: 2 -2c - 1970

