


(SUBMIT IN TRIPLICATE)

Land Office Santa Fe  
Lease No. 079483  
Unit San Juan 30-4 Unit  
14-06-001-1056



UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 24, 1956

Well No. 12 is located 1840 ft. from N line and 1190 ft. from E line of sec. 8  
SW Section 8 30N 4W 100M  
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
E. Blanco P.C. Rio Arriba New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7073 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 10-24-56 T.D. 4133'.

Flugged and abandoned well as follows:

1. Baker Bridge plug @ 4000'.
2. 30 sacks cement plug 4000' - 3800'.
3. Cut casing at 1025' and pulled casing.
4. 25 sacks cement plug 1075' - 975'.
5. 40 sacks cement plug 0' - 120'.
6. Set 4" x 4' pipe marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

By S. Schuler

Title Petroleum Engineer