

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe 078926
Lease No. 078926
Unit I-See, 844
Gallegos Canyon Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	☒	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 24, 19 54

Well No. 66 is located 1970 ft. from N line and 1860 ft. from E line of sec. 35

SW 1/4 NE 1/4 Sec. 35
(1/4 Sec. and Sec. No.)

29N
(Twp.)

13W
(Range)

N.M.P.M.
(Meridian)

West Kuts
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft. (Not available. Will furnish later)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pictured Cliffs Sand test. Estimated depth 1500'.

Surface Casings: 80' of 10-3/4" OD 32# new casing cemented to surface with 80 sacks.

Production Casings: Approximately 1500' of used 6-5/8" OD 20# cemented to surface with 200 sacks.

If commercial production is indicated, the producing section will be shot with nitroglycerin.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BERSON MONTIN

Address 315 1/2 West Main

Farmington, New Mexico

By Albert L. Green

Title Field Superintendent

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
UNITED STATES
(SUBMIT IN TRIPLICATE)

INDICATE ABOVE BY CHECK MARK NATURE OF REPORT (NOTICE OR OTHER DATA)	
NOTICE OF INTENTION TO ABANDON WELL	
NOTICE OF INTENTION TO PULL OR ALTER CASING	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	
NOTICE OF INTENTION TO DRILL	☒
SUPPLEMENTARY WELL HISTORY	
SUBSEQUENT REPORT OF ABANDONMENT	
SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
SUBSEQUENT REPORT OF ALTERNATE CASING	
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
SUBSEQUENT REPORT OF WATER SHUT-OFF	

Well No. _____ is located _____ ft. from _____
 _____ line and _____ ft. from _____
 _____ line of sec. _____

_____ (Range)
 _____ (Twp.)
 _____ (Sec. and Range No.)

_____ (County or Subdivision)
 _____ (State or Territory)


DETAILS OF WORK

DETAILS OF WORK

1. I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company _____
Address _____
City _____
State _____
By _____
Title _____

COMPANY- Benson Montin
LEASE- Gallegos Canyon Unit Well #66
SECTION 35 T29N R13W N.M.P.M.
LOCATION 1970 from north line
1860 from east line
San Juan County, New Mexico



This is to certify that the above plat
was prepared from field notes of
actual surveys made by me and
are true & correct to the best of my
knowledge & belief

Robert L Maddox Jr
Robert L Maddox Jr.
Registered Professional
Engineer & Land Surveyor
N.M. Reg. No 1426

Surveyed 1-31-54